

# DISPOSING P-LISTED & HAZARDOUS MATERIALS



STEP

1

REMOVE THE YELLOW LOCATION BARCODE LABEL AND PLACE IT ON THE DESIGNATED SHEET FOR PROPER DISPOSAL.



STEP

2




FILL OUT AN INDIVIDUAL WASTE LABEL STICKER WITH THE CONTENTS OF THE REAGENT BOTTLE SPELLED OUT CLEARLY. WRITE DOWN YOUR PIS NAME, BUILDING AND ROOM NUMBER ON EACH LABEL.

STEP

3

PLACE THE STICKER ON THE TIGHTLY CAPPED BOTTLE WHILE AVOIDING OVERLAP WITH THE REAGENT LABEL IF POSSIBLE.



STEP

4



LEAVE THE BOTTLE IN A SECONDARY CONTAINER AT A SATELLITE ACCUMULATION AREA FOR PICKUP (ENSURE CONTAINERS ARE PROPERLY SEGREGATED IN THE SAA). YOU CAN REQUEST A FASTER PICKUP THROUGH THE ONLINE EHS INTEGRATOR.